

TABLE OF CONTENTS

LISTING OF PHOTOS, SEGMENTS AND PHOTO DESCRIPTIONS

<u>Segment number</u>	<u>Map photo number and caption</u>
Segment 0	no photo locations on map (photos on file)
Segment 1u	pp1 water quality grab sample site below Gardiner lbpp2, large boulder natural stable banks lbpp4 erosion, bank mass wasting
Segment 1l	pp6 stable bank vegetation Pp8 point bar pebble count Pp10 bank mass wasting Pp12 La Duke Hot Springs Lbpp17 below LaDuke looking upstream Lbpp19 bank mass wasting Lbpp20 bank mass wasting
Segment 2u	pp26 Bridge @ Corwin Springs Pp27 Point Bar Pp28 Bank Mass Wasting below bridge Pp34 Car Body on bank Pp35 blanket rock riprap Pp36 Mouth of Cedar Creek
Segment 2l	lbpp38 stable bank vegetation Rbpp40 rock barbs Rbpp 41 stable bank Rbpp43 stable bank vegetation with backdrop of mountains Rbpp44 older jetty structure with house below Lbpp50 willows stabilizing bank Lbpp54 irrigation pump station on left bank lbpp69 island bank eroded
Segment 3	photo 4 general view Yankee Jim Canyon looking upstream Photo 6 general view Yankee Jim Canyon looking downstream passing through large colluvial material Pp7 Yankee Jim Canyon looking downstream Photo 10 mouth of Tom Miner Creek
Segment 4	pp2 general view looking upstream Rbpp6 stable banks and vegetation Rbpp9 irrigation pumping structure Rbpp10 volcanic rock mass

- Segment 5u pp6 house and eroding bank
 Pp8 large mid-channel bar forming island
 Pp10 blanket rock riprap above rest area. Eroding bank on right
 Pp11 extensive bed material deposition
 Pp14 mouth of Big Creek
- Segment 5m Rbpp17 blanket rock riprap
 Pp18 rock barbs
 Pp21 livestock watering from river
 Lbpp22 Park Branch Canal inlet
- Segment 5l pp23 debris traps sediment building bars and islands
 Rbpp24 blanket rock riprap
- Segment 6u lbpp4 blanket rock riprap
 Lbpp7 eroding bank- fine soils and sod undercut in loose alluvial cobble
 Lbpp 9 barrel revetment
 Lbpp 10 rubber revetment
- Segment 6m lbpp11 concrete wall revetment
 rbpp14 stable bank
 rbpp18 mouth of Mill Creek
 rbpp19 sediment outwash at mouth of Mill Creek
- Segment 6l lbpp23 boulders moved by floodwaters
 Rbpp24 rock barb
 Rbpp25 bank mass wasting
 Rbpp27 bank mass wasting
- Segment 7u lbpp9 point bar cobble count - looking upstream
 Lbpp10 bank eroded by floodwaters
 Lbpp16 bank mass wasting below Mallards Rest Access
 Lbpp17 bank mass wasting below Mallards Rest Access – closeup
 Rbpp5 installing blanket rock riprap
 Rbpp10 irrigation diversion
- Segment 7l rbpp12 rock riprap
 rbpp14 series of rock barbs
 rbpp15 deposition between barbs
 rbpp16 centerline down barb into water
 rbpp20 barb with erosion control fabric
 rbpp24 side channel

pp31 Pine Creek Bridge

- Segment 8u none
- Segment 8l pp35a track hoe placing rock riprap above Carter Bridge
Pp35b work on Carter Bridge to repair bed scour around pier
- Segment 9 Pp3 woody debris
Pp7 90 degree bend in river with riprap on outside
Pp10 river is cutting through transverse bars
Pp13 remainder of circa. 1970's jetty
Pp18 mouth of Billman Creek
Pp22 along I-90 fill, looking east toward Ninth Street Island
Pp25 Livingston riverfront home
- Segment10 Pp1 dike along Sacajawea Park
Pp7 waste travertine slabs used as riprap
Pp11 dike along golf course w/ sandbags
- Segment 11u lbpp5 exposed bedrock below home on bank
Lbpp6 bank mass wasting below home east town
Lbpp7 woody debris jam
- Segment 11l rbpp5 dike
Rbpp7 root armor on bank
Rbpp12 rock riprap on toe of Hwy bridge
- Segment12u pp2 eroded bank
- Segment12l none
- Segment 13u rbpp15 good example of natural vegetation providing bank protection
rbpp16 scoured/exposed roots of mature cottonwood trees
- Segment13m pp20 Great Blue heron colony in mature cottonwood gallery
- Segment 13l pp21 irrigation canal headgate
Lbpp22Car body on bank. Crazy Mountains in background
Lbpp23 eroding bank. Old channel blocked
Pp25 Springdale Bridge – end of the float trip!!

General slides:

- 05 Rafter near Gardiner
06 Kayaking near Gardiner
12 Absorka Mountains to the East of Yellowstone River – North of YNP

13 “ “ “ “ “ “ “ “ “ “

18 drift boat crew inventory

Seg3 #2 Yankee Jim Canyon –morning light

Seg8l #01 Massive rock of size used to armor banks of Yellowstone River

Seg10 #22 junk dumping spot on bank

Seg11l #19 working float

Seg 11 #28 putting in the drift boats with guides

Seg 11 #36 drift boat warning sticker

Seg12 #06 mature cottonwoods no understory vegetation. Bank undercut and eroded during last flood event

Seg 12 #22 sandy material deposited during last flood event

Seg12 #08 discussing the days mapping results

Seg 12 #32 out of the mountains and into the plains changes the nature of the river