

Better Answers Now Not Later

Prioritizing Workflows w/ Al/ML on Aerial Imagery


Mark Davis
General Manager
Vexcel Government Solutions
Mark.Davis@Vexcelgroup.com




Agenda

- Trends in Aerial Imagery
- Imagery "Stack" and Coverage
- Extracting Insights
- High Impact Use-Cases


No silver bullet
and
Understanding needs will drive
selection process







Growing Utilization of High-Resolution Imagery & Analytics




About Vexcel

30 years of photogrammetric excellence Aerial content across 30 countries Data histories back to 2016

Growing AI/ML library (w/80+ features)

Vexcel Data Program



Vexcel Fleet












Existing U.S. Footprint: 3 million sq mi



Largest collection of its kind with:

- √ Unmatched accuracy
- √ High-resolution aerial imagery
- √ Consistency across imagery





49 states

Urban & rural collections



99.6% U.S. population




households




Current and Historical Imagery & Analytics across Montana









Urban imagery collected 2X per year: 3 inch, 4 Band Ortho, Obliques & DSM/DTMs

Statewide imagery collected 1X per 2 years: 6 inch. 4 Band Orthos & DSMs





Imagine if you could prioritize top issues across your entire State





Feature Extractions: Infrastructure, Roadway, Building & Property Elements







Building Attributes

- 20+ building and structure attributes
- Available for current and historic imagery


Property Attributes

- 20+ attributes, including footprint area, roof condition, solar panels, and pools
- Available for current and historic imagery

Damage Assessment

- Post-disaster analysis on impacted properties
- Available for all Gray Sky collection from 2022 and forward





Building Attributes	Value
Footprint area	4,626.65ft ²
Ground elevation	527.03 ft
Roof elevation	553.08 ft
Roof height	28.15 ft
Roof Centroid	-74.287889 40.800163
Tree cover over roof	0%
Roof solar	No
Chimney(s)	1
AC unit(s)	0
Roof vent(s)	11
Satellite dish(es)	0
Skylight(s)	6
Roof shape	Hip
Roof material	Shingle
Missing roof material	0%
Roof condition	4/5
Roof discoloration	1.35%
Vent staining	No – 0%
Algae staining	No – 0%
Water pooling	No – 0%
Roof tarp	0%
Debris	0%





Property Attributes	Value
Pool	Yes – 1013.96 ft ²
Pool: In ground-area	Yes – 908.04 ft ²
Pool: Above ground	No - N/A
Hot tub – area	Yes – 106.99 ft ²
Diving board	No
Water slide	Yes
Deck	Yes
Playground	Yes
Trampoline	No
Sports court	No
Hardscapes	Yes - 5898.62 ft ²
Vehicles: automobile	1
Vehicles: boat	0



Primary Defensible Space




Analysis based on 12 October 2022 imagery


Defensible Space	Value
DSB 5 ft	0%
DSB 30 ft	0%
DSB 100 ft	13%
DSB 200 ft	14%
DST 5 ft	9%
DST 30 ft	9%
DST 100 ft	11%
DST 200 FT	12%

Defensible Space Building: DSB Defensible Space Trees: DTS

Metrics above relate to 5, 10, 30 100, and 200 foot buffers for both buildings and trees; ex: 24% of the 100 foot buffer contains other buildings











Damage Assessment for 3.6 Million Buildings

• Automatically generated catastrophe analytics on freshly captured disaster event imagery










Damage Assessment


Our AI analysis identified a total of 2,760 structures within our Lahaina collection area.

- 1,718 structures were completely destroyed; 62% of all the structures in the collection area
- 363 structures had slight to moderate damage, ranging from some fire damage to missing shingles possibly caused from the severe winds that fanned the fires.
- 678 structures had no damage identified in the imagery





Feature Extractions: Roadway Elements



Pavement Markings

- Crosswalks
- Bicycle symbols
- Arrows
- Words
- Available for current and historical imagery


Infrastructure

- · Pedestrian refuge islands
- ADA truncated domes "curb mats"
- · Intersection-junctions
- Available for current and historical imagery


Condition Assessment

- Pavement marking quality score for prioritizing maintenance
- Available for current and historical imagery

Digitizing Transportation Infrastructure for...



AI/ML Object Detection and Classification







Safety Benefits:

High-visibility crosswalks can reduce pedestrian injury crashes up to:

40%

Intersection lighting can reduce pedestrian crashes up to:

Advance yield or stop markings and signs can reduce pedestrian crashes up to:






U.S. Department of Transportation Federal Highway Administration

Crosswalk Compliance Assessment: Low vs. High Visibility





Crosswalk Condition Assessment





Pavement Condition Scoring




Scored between 1-4 based on pavement marking imagery classified using subjective condition assessment markings.

- 4 = Great. No visible signs of defects.
- 3 = Good. Minimal signs of defects.
- 2 = Fair. Pronounced signs of defects that affect the function of the marking.
- 1 = Poor. Pronounced signs of defects that significantly affect the function of the marking.



Maintenance Planning – Pavement Markings

Item (Tag)	Count	Poor Condition Count	Replacement Cost (Materials)	
stopbar	4235	333	32967	
straight_arrow	3848	528	78672	
leftturn arrow	5569	154	26180	
rightturn_arrow	1870	81	13770	
cw_diagonal	123	3	3000	
cw ladder	396	37	37000	
cw zebra	100	3	3000	
handicap_symbol	856	0	0	
straightleft_arrow	198	8	2592	
cw solid	219	11	8250	
cw_standard	1349	196	88200	
leftright_arrow	33	5	850	
ONLY_text	419	39	10998	
STOP_text	122	10	2550	
straightright_arrow	522	37	11988	
bikesymbol	459	0	0	
merge_arrow	299	8	3696	
AHEAD_text	7	0	0	
allway_arrow	15	1	447	
BUS_text	4	0	0	
LANE_text	2	0	0	
PED_text	1	0	0	
RXR	120	17	8364	
SCHOOL_text	138	18	6480	
sharedlanebike	122	0	0	
SIGNAL_text	2	0	0	
text_other	28	1	200	
uturn_arrow	12	0	0	
XING_text	2	0	0	
YIELD_text	6	2	558	
Yieldbar	30	3	169.5	
	21160	1495	\$339,932	



Poor condition road markings with quality score of 1 within city limits. Model version 06/07/23







Pedestrian and Bicycle Markings























Roadway Data from High-Resolution Aerial Imagery

Roadway Inventories for Bike and Pedestrian Facilities

- Crosswalks (standard and high visibility) at intersections and midblock
- Bicycle lanes (symbols, words and green painted lanes)
- ADA detectable curb mats (truncated dome) and pedestrian refuge islands

2. Roadway Inventories for intersections and approaches

- Exclusive Left-turn and Right-turn lanes
- Presence/Absence of crosswalks
- Presence/Absence of bicycle facilities

3. Condition Assessment of Road Markings for Maintenance Prioritization

- Identification of faded or worn pavement markings
- Development of predication models based on historic imagery


4. ADA Compliance Assessment

Mapping of required detectable warnings on curb ramps per DOT ADA standards

5. Confirm and Document Installation of Countermeasures

Creation of as-builts for FWHA proven Pedestrian/Bicyclist countermeasures¹ (e.g., high-visibility crosswalks, advance stop and yield lines, ped. refuge islands).







Statewide Needs

High value source imagery

Mapping grade quality & accuracy

Increased savings

Buy-up options

Tiered Government & Public Access

Standard formats for easy integration

		Package Items		
	Product Info	Starter Package	Standard Package	Complete Package
Rural & Urban	6in Wide Area Orthos	✓	✓	✓
Blue Sky	6in Wide Area Derived DTM/DSM			\checkmark
	6in Wide Area Ortho Multispectral	✓	✓	✓
	3in Urban TrueOrthos	✓	\checkmark	\checkmark
Urban	3in Urban Obliques	✓	\checkmark	\checkmark
Blue Sky	3in Urban Ortho	✓	\checkmark	\checkmark
	3in Derived DSM			\checkmark
	3in Urban TrueOrtho Multispectral	✓	\checkmark	\checkmark
	3in Urban Ortho Multispectral	✓	✓	✓
Disaster/ CAT Events	Gray Sky Imagery	✓	✓	✓
Gray Sky	Post disaster property analytics		✓	✓
	Building Footprints w/ sq. footage & pools		\checkmark	\checkmark
Elements AI/ML based feature extractions	Building Attributes			\checkmark
	Property Attributes			\checkmark
	Roadway Attributes			✓
Services, Archives & Data Rights	Historical Data Library	✓	\checkmark	\checkmark
	Connectors (ESRI, WMTS, Map Controls, APIs, Viewer)	✓	✓	✓
	Data viewable in public website views & Government Tier Access	✓	✓	✓
	Professional Services—Vexcel Advocacy	✓	✓	✓

Dackage Items

In summary



Hi-Res **Aerials**



30+ Countries



Post-CAT Imagery





Damage Assessment





Property Attributes



Unmatched Accuracy



Flexible Memberships



Building **Attributes**



Support Across **Property Life** Cycle



API & GIS Integrations



Top-Class Support



Partner **Network**



Urban + **Rural Areas**

