

INSTRUCTIONS

1. Original and/or subsequent record locate the corner position.
2. Description of evidence found, notes, and sketches in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner 23|24 / 26|25 T. 20 N., R. 26 W., P.M.M. Sanders County

RECORD: "YEAR" 1947

Set an Iron post 3 ft. long, 2 ins. diameter, 26 ins. in the ground, over a stone marked with a cross (x), with brass cap marked as shown:

T 20 N
 S 23 | S 24
 S 26 | S 25
 R 26 W
 1947

Raised mound of stone 4 ft. base, 2 ft. high west of corner.

FOUND:

A 2 in. Iron pipe with 2 1/2 in. brass cap, 6 ins. above ground marked as shown:


T 20 N
 S 23 | S 24
 S 26 | S 25
 R 26 W
 1947

MAINTENANCE:


Placed Land Survey Monument sign on post near corner

DECLINATION USED - 19° E.

74



SKETCH OF CORNER



CERTIFICATION

I, _____
 certify the information shown herein is true and correct.

Signature Ground Party Chief

I, James A Flansburg

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22101, et seq., M.C.A.)

Signature of Surveyor & Seal

Date: 2-5-88 Reg. No. 8643 S

Employer: USFS

Office of Clerk and Recorder, County of Sanders. This "corner record" Sec. 26

was filed for record on the 7 day of April 1988, was noted on the cross-index plat and is assigned page No. 3, in book No. 74

County Official

by Evelyn Cox

Cross Index No. R21 T. 20 N R. 26 W P.M.M.

