Premier Data Services v1.0.2

## PLSS Corner Collection System Data Sheet

Meridian: PMM Tier: 3N Range: 59E Section(s): 22, 23, 26, 27 County: Fallon

GCDB Point ID: M T 2 0 0 0 3 0 N 0 5 9 0 E 0 5 0 0 3 0 0

Employee Name: Ryan Dee Date: 6/23/2011 Time: 4:30

Found: A steel pipe fence corner post, 8" diameter, 4' above ground. This post was set by Ken Jacobson, whose grandfather homesteaded in section 26. Ken's father told him that the location for the section corner was at the current location of said steel pipe. While Ken was auguring his hole for the corner post he hit a 'steel rod with a metal cap that had markings on it', he put the pipe and cap at the bottom of his augured hole. Monument is situated at the intersection of fences South, West, and Northeast. Monument is on Southwest edge of driveway bearing Northwest and Southeast.



Latitude: 45°59'47.6599" N Longitude: 104°22'11.0653" W Datum: NAD83(2007)

Approximate orthometric elevation: 3329 ft.

This corner was located as part of a PLSS enhancement project. The location of this corner was not used as control for any legal surveys during this exercise. Horizontal accuracy 1 meter or less.