

STATE OF MONTANA
DEPARTMENT OF NATURAL RESOURCES AND CONSERVATION
1424 9TH AVENUE P.O.BOX 201601 HELENA, MONTANA 59620-1601

GENERAL ABSTRACT

Water Right Number: 76H 124210-00 STATEMENT OF CLAIM
Version: 1 -- ORIGINAL RIGHT
Version Status: ACTIVE

Owners: BOLIN RANCHES
1356 BOLIN RANCH RD
STEVENSVILLE, MT 59870-6256

Priority Date: MAY 31, 1898
Enforceable Priority Date: MAY 31, 1898

Type of Historical Right: FILED

Purpose (use): STOCK

Maximum Flow Rate: A SPECIFIC FLOW RATE HAS NOT BEEN DECREED BECAUSE THIS USE CONSISTS OF STOCK DRINKING DIRECTLY FROM THE SOURCE, OR FROM A DITCH SYSTEM. THE FLOW RATE IS LIMITED TO THE MINIMUM AMOUNT HISTORICALLY NECESSARY TO SUSTAIN THIS PURPOSE.

Maximum Volume: THIS RIGHT INCLUDES THE AMOUNT OF WATER CONSUMPTIVELY USED FOR STOCK WATERING PURPOSES AT THE RATE OF 30 GALLONS PER DAY PER ANIMAL UNIT. ANIMAL UNITS SHALL BE BASED ON REASONABLE CARRYING CAPACITY AND HISTORICAL USE OF THE AREA SERVICED BY THIS WATER SOURCE.

Source Name: GRAYHORSE CREEK
Source Type: SURFACE WATER

Point of Diversion and Means of Diversion:

<u>ID</u>	<u>Govt Lot</u>	<u>Qtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rge</u>	<u>County</u>
1		S	WSENE	7	9N	18W RAVALLI

Period of Diversion: JANUARY 1 TO DECEMBER 31
Diversion Means: HEADGATE

Period of Use: JANUARY 1 to DECEMBER 31

Place of Use:

<u>ID</u>	<u>Acres</u>	<u>Govt Lot</u>	<u>Qtr</u>	<u>Sec</u>	<u>Twp</u>	<u>Rge</u>	<u>County</u>
1				SE	6	9N	18W RAVALLI

Geocodes/Valid: 13-1766-06-1-01-01-0000 - Y

Remarks:

THE WATER RIGHTS LISTED FOLLOWING THIS STATEMENT ARE MULTIPLE USES OF THE SAME RIGHT. THE USE OF THIS RIGHT FOR SEVERAL PURPOSES DOES NOT INCREASE THE EXTENT OF THE WATER RIGHT. RATHER IT DECREES THE RIGHT TO ALTERNATE AND EXCHANGE THE USE (PURPOSE) OF THE WATER IN ACCORD WITH HISTORICAL PRACTICES.

124208-00 124210-00

THE PRIORITY DATE WAS AMENDED BY THE CLAIMANT ON 05/10/1989.

STARTING IN 2008, PERIOD OF DIVERSION WAS ADDED TO MOST CLAIM ABSTRACTS, INCLUDING THIS ONE.

OWNERSHIP UPDATE RECEIVED

OWNERSHIP UPDATE TYPE 608 # 115974 RECEIVED 11/12/2013.

IT APPEARS POINT OF DIVERSION NO. 1 MAY BE INCORRECT. THE EXISTENCE OF A DIVERSION FACILITY AND CONVEYANCE DITCH CANNOT BE CONFIRMED FROM AVAILABLE DATA.