

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner NW cor. Sec 5 - NE cor Sec 6 T. 36N R. 27W P.M.M. Lincoln County


Record:

Set a sandstone 16x10x10 " 11" in the ground. with 5 notches on east face and 1 notch on west face

Dug pits for R.M.s.

Found stone as described - set metal fence post alongside.

See C.of S. No 541 for adjacent corners



SKETCH OF CORNER

CERTIFICATION

I, _____
 certify the information shown herein is true and correct.

Signature Ground Party Chief
D.K. Marquardt

I, _____
 certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)


D.K. Marquardt
 Signature of Surveyor & Seal

Date: 7-6-81 Reg. No. 2989ES

Employer: _____

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the 17th July day of 1981, was noted on the cross-index plat and is assigned page No. 1152, in book No. 1

Glenn L. Vaughn, by Betty Bell,
 County Official Deputy



Cross Index No. A-5 T. 36N R. 27W P.M.M.

● - corner this sheet