

INSTRUCTIONS

1. Original and/or subseq. record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

-CERTIFIED CORNER RECORDATION

Corner 1/4 cor. Section 7 T. 36N R. 26W P.M.M. Lincoln County
 Section 12 T. 36N R. 27W


Record: Set a limestone 16x12x10 ins in the ground from which:

- a pine 15" diam. bears S80°E. 142 lks.
- a pine 14" diam. bears S55°W. 86 lks.

No evidence of original corner found.

Set brass cap at fence corner

See C.O.S. No. 821 for adjacent corners



SKETCH OF CORNER

CERTIFICATION

I, _____ certify the information shown herein is true and correct.

Signature Ground Party Chief

I, D.K. Marquardt certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)


D.K. Marquardt
Signature of Surveyor & Seal

Date: 7-10-81 Reg. No. 2389ES

Employer: _____

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the 12th August day of 1981, was noted on the cross-index plat and is assigned page No. 1202 in book No. 1

Deborah L. Vaughn, by Betty Bell,
County Official deputy



Cross Index No. G-25 T. 36N R. 27W PMM
G-1 T. 36N R. 26W

• - corner this sheet