CERTIFIED CORNER RECORDATION

Corner _____ ¼ Section 17 - 20 _____ T. __ 4 N __ R. __ 10 W __ P.M.M. __Anaconda-Deer Lodge__ County

ORIGINAL: GLO SURVEYOR, Walter Johnson, Contract 28, Aug. - Sept. 1869, at 40.00 chains set ¼ section corner, a post in mound of earth with pits, charred stake as per instructions.

SUBSEQUENT: Bonneville Power Administration (approx. 1950) subdivided Section 17 for the establishment of their substation, located in the west one-half of Section 17. Monumentation was established and is also shown upon the J.E. Monk, plats (12-6-1960). Set an iron pipe.

SUBSEQUENT: COS 100C, found iron pipe.

FOUND: 1" iron pipe, no cap.

PERPETUATION: Set 3/4" x 30" rebar, with 3¼ aluminum cap, marked as shown, in position of found iron pipe. Set 4' steel post 1.0' west with MARLS tag.

Verification of corner position was completed by use of BPA's listed coordinate data and this (1998) survey information.

See COS _____ 238 A _____ for sectional breakdown information.

SKETCH OF CORNER

T4N R10W

¼ — 17 / 20

MILAM 1998 9007

(Seal: MONTANA — RONALD D. MILAM 9007 S — LICENSED PROFESSIONAL LAND SURVEYOR)

CERTIFICATION

I, __KURT LUEBKE__
certify the information shown herein is true and correct.

Kurt Luebke
Signature Ground Party Chief

I, __RONALD D. MILAM__
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

Ronald D. Milam
Signature of Surveyor & Seal

Date: __APRIL 1998__   Reg. No. __9007__

Employer: __Druyvestein Johnson & Anderson__

Office of Clerk and Recorder, County of __Anaconda-Deer Lodge__. This "corner

record" was filed for record on __JUNE 17, 1998__

was noted on the cross-index plat and is assigned Page No. __513__, in

Book No. __2__.

Barbara J. Vaughn, DEPUTY
County Official

Sec. 17

Cross Index No. __N-7__ T. __4 N__ R. __10 W__ P.M.M.   ● corner this sheet