

117469  
CERTIFIED LAND CORNER RECORDATION  
(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

RECORD: Set 1/4 Section Corner, a post in mound of earth with pits and charred stake as per instructions.  
FOUND: No evidence of original corner. I accepted the proportioned position as established between corners 1/2 mile east and west.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


Date of work: 6/18/81

Set a 2" brass cap on a 1" pipe flush with ground marked as shown below.  
A nail in top of a post with K tag bears N56°E 56.63 ft.  
A nail in top of a post with K tag bears S56°E 45.95 ft.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

SEE CERTIFICATE OF SURVEY NO. 42A

Surveyor's Seal



I, CLINTON W. HARRIS  
certify that the information shown herein is true and correct.


*Clinton W. Harris*  
Signature of Ground Party Chief

I, THOMAS M. HANSON  
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

*Thomas M. Hanson*  
Signature of Surveyor

3153ES  
Registration Number

DIAGRAM OF CORNER:



= Corner recorded on the sheet

Office of Clerk and Recorder, County of *Deer Lodge*  
his "corner record" was filed for record on the *7th* day of *July*, 19*81*, was noted on the cross-index plat and is signed page No. *233*, in book No. *1*  
CLERK & RECORDER  
ANACONDA-DEER LODGE COUNTY  
ANACONDA, MT 59711  
Cross Index No. *J-11* T. *5 N* R. *10 W.P.M.* Mer.