

Missoula County Control Point Datasheet

Monument Description: 3-1/4" Aluminum Cap 10998S

Project Name: ALL

Station Description: Section Corner

Date Visited: July 12, 2010

Monument Stability: C GPS Visibility: A

Observer: SEN

Quad. Name: Primrose

T. 14 N.

R. 21 W. R. 20 W.

24	19
25	30

NAD 83 (2007) Lat/Long Position

46°57'01.632"N

114°11'14.880"W

NAVD 88 Elevation: 3063.9 sft.

Notes:

Photo of Monument



Photo Looking East



Photo Looking West



To Reach: 2wd access.



Map of Area

- INSTRUCTIONS**
1. Original and/or subsequent record used to evaluate the corner position.
 2. Description of monument and accessories set to perpetuate the corner position.
 3. Sketch of corner showing all pertinent data which can best be shown in a sketch as appropriate, accessories, etc.
 4. Fill in Cross Index & Section Diagram at bottom of sheet.
 5. Fill in Cross Index & Section Diagram at bottom of sheet.
 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner Common to Sections 19, 30, 24 and 25
 T. 14 N. R. 20 W., and T. 14 N. R. 21 W. P.M., M. Missoula County, Montana
RECORD #1: (September 19, 1870) G. L. O. survey by Walter W. Johnson and William H. Baker
 "Set cor. to sec. 19, 24, 25, 30, a post in mound of earth, with pits, charred stakes etc as per instructions."

RECORD #2: (June 14, 1973) Corner Recordation Form #333904, by William D. Bayer
 "Reestablished this corner by single proportion measurement between the found section corner common to sections 25, 30, 31 and 36, and a call in the original notes to O'Keefe Creek. Used existing fence lines running north and south to control the departure. Local residents accept this fence as being the true township line."

Set a 1 1/2" diameter brass cap marked as shown in the north shoulder of a 20' dirt road.
 A fence post with a MARLS corner tag attached bears Due South, 20.5'.
 A fence post with a MARLS corner tag attached bears N19°W, 7.6".

RECORD #3: (March 13, 2009) Certificate of Survey #6142, by Montana Northwest Co.
 "FOUND 3/4" REBAR, NO CAP"

FOUND: (July 12, 2010) A 1/2" copper clad bar, 8" below the surface of Mocassin Lane.

SET: I epoxied a 3-1/4" Aluminum Cap to the found 1/2" bar, marked as shown. The corner is just north of the centerline of Mocassin Lane.

No suitable objects were available for reference.

NAD 83 (2007) Lat. Lon. NAD 83 (2007) SPC Intl. Ft. Positional information determined by static GPS observations, with ties to MSOL, D509, and N371, using NAVD88 elevation 3063.9 sft Missoula Co. GPS #5837

CERTIFICATION
 I, Steve Niday, certify the information herein is true and correct.

Signature of Surveyor: *Steve Niday*
 Date: 10-9-10
 Reg. No. 10098LS
 Employer: Missoula County Public Works, Survey Office

Signature of Client: *Steve Niday*
 Date: 10-9-10
 Reg. No. 10098LS
 Employer: Missoula County Public Works, Survey Office

Section Diagram:
 A grid showing sections 19, 24, 25, and 30. A red dot is located at the intersection of sections 19 and 25, representing the corner location. The diagram is labeled "SET 3-1/4" AL CAP" and "12500 Mocassin Ln".

201019170 B: 866 P: 1263 Passes: 1
 10/04/2010 10:05:32 AM Corner Recordation
 Vickie R. Baker, Missoula County Clerk & Recorder

Cross Index No. R-25 T. 14 N., R. 21 W. P.M., M.
 R-1 T. 14 N., R. 20 W.
 • corner this sheet

Corner Recordation Form or Other Supporting Document