

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Standard Corner Sections 33 & 34 T. 25 N. R. 18 W. P.M.M. Lake County

ORIGINAL RECORD: (1935 G.L.O.) Not recovered.

EVIDENCE FOUND: Found 2½" brass cap, 0.65' above ground.


Monument lies 15.5' up hill from top of cut slope and approximately 50' west of Porcupine Creek Road.
A 24" pine bears S28°E, a distance of 6.0 ft, found tag affixed.

PERPETUATION: Left monument as found.

Date of Survey: October, 2010.



NAD 83 coordinates for this corner:
Latitude = 47°52'39.79"N Longitude = 113°52'41.17"W
NOTE: These coordinates are to be used as a search tool only.



CERTIFICATION

I, Steve Cummings
certify the information shown herein is true and correct.

Signature Ground Party Chief

I, Kurt A. Luebke
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

Signature of Surveyor & Seal

Date: 11-22-2010 Reg. No. 13237 S

Employer: DJ&A P. C.

