INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.

Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

Description of monument and accessories set to perpetuate the corner position.

Sketch of corner, show all pertinent data which can best be shown in a sketch example, comer marking, topography ties, position of accessories, etc

Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner 1/4 COR SECS 7 & 8

T. 33N., R. 6W., P.M.M.

Glacier County

RECORD GLO 1907

Set a granite stone 14"x10"x5", 10" in the ground for 1/4 section corner, marked 1/4 on the West face. Dig pits 18"x18"x12" North and South of corner, 3' in distance. And raised a mound of earth, 3 1/2' base, 1 1/2' high, West of corner.

RECORD GLO 1922


Found a granite 4"x2"x1" above ground, marked and witnessed as described by the Surveyor General. West of stone, and 1/4 link distance, is an iron pipe, 2" in diameter, 10" above ground, for corner of allotments "770, 767,2120 & 2122", with the numbers of the allotments stamped on the sides.

RECORD G.G.DUBOIS <u> 1999</u>

Found a 2" iron pipe, no cap, buried 0.3' below ground, 6' south of an East/West canal, 10' North of fence corner North-South-East, in the North-South fence line. Stone not recovered. Uncover pipe, build 1' collar of stone, stake and flag area.

FOUND MDT 2000

Found 2" iron pipe flush with ground, approximately half-way up slope on the South side of irrigation ditch, running East/West. Pipe is 15.85' North of fence corner, of 4' high fence running South, North and East. Pipe is 7.55' South of gate post (for drop gate) at South top of bank of irrigation ditch.



core 2. Land Curvayers

6-5 7.33 Rb

corner this sheet