

**INSTRUCTIONS**

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography lies, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

**CERTIFIED CORNER RECORDATION**

Corner  $\frac{1}{4}$  CORNER  $\frac{16}{21}$  T. 4 N R. 10 W P.M.M. DEER LODGE County

G.L.O. SURVEY COMMENCED 8-27-1869 BY: W. JOHNSON

**RECORD:**

SET  $\frac{1}{4}$  SEC. COR. A POST IN MOUND OF EARTH WITH PITS  
CHARRED STAKE, AS PER INSTRUCTIONS


**FOUND:**

NO CORNER EVIDENCE FOUND

**SET:**

A  $2\frac{1}{2}$ " ALUM. CAP ON  $\frac{3}{4}$ " X 24" REBAR, WITH A  
NO. 7 X 5 FT. REBAR BESIDE IT.

**MARKED:**



SEE CERTIFICATE OF SURVEY NO. 100C  
FOR REFERENCE TO ADJACENT CORNERS  
CORNER RE-ESTABLISHED BY SINGLE PROPORTIONMENT

SKETCH OF CORNER

**CERTIFICATION**

I, \_\_\_\_\_ certify the information herein to be true and correct.

\*A Registered Land Surveyor in Montana

GORDON

I, GORDON certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the Corner Recordation Act (70-224-101 et seq. M.C.A.)

Date: 3/27/1996 Section No. 2345 ES

Employer: \_\_\_\_\_

Office of Clerk and Recorder, County of DEER LODGE. This "corner record" was filed for record on the March 29 day on 1996. was noted on the cross-index plat and is assigned page No. 418, in book No. 2

County Official

Sec. 21
