

Missoula County Control Point Datasheet

Monument Description: 2" Aluminum Cap 13603S

Project Name: ALL

Station Description: 1/4 Corner


Date Visited: July 13, 2010

Monument Stability: B GPS Visibility: A

Observer: SEN

Quad. Name: Primrose

T. 14 N. R. 20 W.



NAD 83 (2007) Lat/Long Position

46°57'01.462"N

114°08'05.375"W

NAVD 88 Elevation: 3277.8 sft.

Notes:

Photo of Monument



Photo Looking North



Photo Looking South



To Reach: 2wd access, monument falls on edge of exit ramp.



Map of Area

Q:\CO-STD-152
Revised 1/17/96

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Accessories, etc. Show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

S 1/4 Corner, Cor. Sec. 21 T. 14 N. R. 20 W P.M.M. MISSOULA County


Original Record -
GLO - 1870
W. Baker

Subsequent Record Found - MDTI 2004
Set 1 - MDTI 2004

Set 1/2 sec. cor. a red sandstone 14x9x6 ins. with pils, marked stone as per instructions
CCR 447229 and COS 1466 - Set 2 1/2" Brass Cap at proportionate measure

Nothing - New interstate off-ramp destroyed all evidence of corner.

Set 2" MDT Aluminum stamped cap on 24" rebar driven 1/2" below surface of asphalt at single proportionate position with references as shown below.



CERTIFICATION
I certify the information shown above is true and correct.
Signature of Land Surveyor
L. David M. Hodgson, D. DAVID M. MONTANA
I, David M. Hodgson, a duly Licensed Professional Engineer, certify that this Corner Recordation work was performed by me or under my direct supervision and that I am a duly Licensed Professional Engineer with the Corner Recordation License No. 980270 of the State of Montana (MCA).
Signature of Engineer
Date: 10/04
Employer: MDT

SKETCH OF CORNER
Office of Clerk and Recorder, County of Missoula
This "corner record" was filed for record on _____, was noted on the cross-index plat, and is assigned Page No. _____, in Book No. _____
County Official
Sec. 21
Cross Index No. R511, 15M R. 20W P.M.M.
200430791
Page No. 111, Book No. 328
Missoula County Victor P. Zaster, CL
BK-742 Pg-884
DRD.DD.O.PS.LC