

Missoula County Control Point Datasheet

Monument Description: 2" Brass Cap 2923S

Project Name: Seeley Lake

Station Description: 1/4 Corner


Date Visited: Aug. 17, 2010

Monument Stability: C GPS Visibility: C-

Observer: SEN - CLG

Quad. Name: Belmont Point

T. 16 N. R. 15 W.



NAD 83 (2007) Lat/Long Position

47°06'21.955"N

113°31'32.891"W

NAVD 88 Elevation: 4192.5 sft.

Notes:

Photo of Monument



Photo Looking East



Photo Looking West



Point # 5875

To Reach: 2wd access.



Map of Area

245-11141

INSTRUCTIONS

1. Original and/or subsequent record file, show the corner position.
2. Description of evidence found, note observations in the record, bear monuments or other natural corners.
3. Sketch of corner, show all pertinent data which can best be shown in a sketch example: corner marking, topography etc, position of monuments, etc.
4. Certification must be signed and dated by Registered Land Surveyor or State of Missouri.
5. If in Cross Ties, A Section Diagram or Section of Same.

CERTIFIED CORNER RECORDATION

Corner 29 32 T. 16 N. R. 15 W. P.M.M. Missouri County

1890 (GLO) "Set a sandstone, 20 x 12 x 6 ins., 15 ins. in ground for the 1/4 corner, marked 1/4 on North face; from which
A pine, 9 ins. diam., bears S. 36° 30' E., 28 lbs. dist... marked...
A pine, 10 ins. diam., bears North, 58 lbs. dist., marked...."

1986 (PCI) I find no evidence of original 1/4 corner monument or original bearing trees. Existing County Road appears to have destroyed all original evidence.

By single proposition, I set a 2" brass cap on a 1" iron pipe, 6" below the surface of the South Placid Lake Road (gravel). Said corner falls on the Southernly edge of the road. Brass cap marked as indicated below. From said monument;

A 12" larch bears North, 77.54 feet, scribed "91" w/bearing tree tags.
A 6" larch bears S. 44° E., 29.11 feet, scribed "91" w/bearing tree tags.

30	29	2640' (GLO record)	29	2640' (GLO record)	29	28
31	32	2653.98' (found)	32	2653.98' (found)	32	33
5280' (GLO record) S. 89° 54' 55" E., 5307.29' (found)						

1/4 Corner shown on this form

BRASS CAP MARKINGS



12" larch → North 77.54'

Set 2" Brass cap on 1" iron pipe - 6" below road surface

SOUTH PLACID LAKE ROAD

S. 44° E. 29.11' larch

29.11'

SKETCH OF CORNER

CERTIFICATION
I, Richard A. Agamirovich, Registered Professional Surveyor, certify that the above shown is true and correct.

Richard A. Agamirovich
1922 MISSOURI REGISTERED PROFESSIONAL SURVEYOR No. 2923S

PROFESSIONAL CONSULTANTS, INC.
1000 S. GURVE

Office of Clerk and Recorder, County of Missouri. This "corner record" Sec. 29

was filed for record on the 19th day of August, 2011, was noted on the cross-index plat and is assigned page No. 441, in book No. 245-11141 by Fern Hall County Official

Doc: CR Infan County Official Infan

Corner Index No. U-7 T. 16N R. 15W P.M.M. corner this sheet

8611971

Corner Recordation Form or Other Supporting Document

Point # 5875