



INSTRUCTIONS

61-289813

- 1 Original and subsequent record used to evaluate the corner position.
- 2 Description of monument found, note discrepancies in the record, state method of setting lost or obliterated corners.
- 3 Description of monument and accessories set to perpetuate the corner position.
- 4 Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5 Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
- 6 Fill in Cross Index & Section Diagram at bottom of sheet.


CERTIFIED CORNER RECORDATION

Corner Sec. 6 | 5 7 | 8 T. 16 N. R. 19 W. P.M.M. Lake County

GLO RECORD: (1905) Set a granite stone 16x12x8 ins., 12 ins. in the ground, for the cor. of secs. 5, 6, 7 and 8, marked with 5 notches on S. and E. edges; raise a mound of stone 2 foot base, 1½ ft. high, W. of cor., pits impracticable.

FOUND: No evidence found. Corner position falls in proximity of county road.

SET: Establish corner position by double proportionment, set 2"x24" iron pipe with 2" brass cap marked:



See reverse side for ties to adjacent corners.

SKETCH OF CORNER

CERTIFICATION

I, \_\_\_\_\_ certify the information shown herein is true and correct.

Signature of Ground Party Chief

I, Gordon E. Johnson certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.).

Signature of Surveyor & Seal

Date: 5/13/85 Reg No. 2345ES

Employer: \_\_\_\_\_

Office of Clerk and Recorder, County of Lake. This "corner record" was filed for record on the 15th day of May, 1985 at: 1:00 P.M. was noted on the cross-index plat and is assigned Microfilm No. 289813

By: LORIN JACOBSON CLERK & RECORDER  
Roxanne Cooper, Deputy County Official

File No. C-1433

