

CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

see reverse side and plat of Mission View Ranchos

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: MAY 19 1973

see reverse side and plat of Mission View Ranchos

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

see reverse side and plat of Mission View Ranchos

DIAGRAM OF CORNER:


Surveyor's Seal

I, \_\_\_\_\_ certify that the information shown herein is true and correct.


Signature of Ground Party Chief

I, HARRY P. MEDLAND certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Harry P. Medland Signature of Surveyor



• = Corner recorded on the sheet



22295 Registration Number

Office of Clerk and Recorder, County of Lake, State of Montana

This "corner record" was filed for record on the 18th day of February 19 75, at 11:49 o'clock A. M., was noted on the cross-index plat and is

signed ~~xxxx~~ Micro. 220786, in book No. C-545

Ethel M. Harding, Clerk & Recorder

County Official BY: Ethel M. Harding, Del

Cross Index No. A-7 C-9 E-7 C-7 T. 22 N. R. 20 W. Mer.

