

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner Sections 21, 22, 27 & 28 T. 25 N. R. 18 W. P.M.M. Lake County

ORIGINAL RECORD: (1935 G.L.O.) Not recovered.

EVIDENCE FOUND: Found 2½" brass cap, 0.6' above ground, slightly leaning south.

Monument lies approximately 280 ft. east of Crane Mt. Road and approximately 35 ft. southeasterly of a stream.


A decomposing stump BT bears N14°E, a distance of 25.0 feet.

PERPETUATION: An 18" Lodgepole pine bears S79°W, a distance of 30.3 ft., affixed BT tag.  
A 12" fir bears S56°E, a distance of 13.7 ft., affixed BT tag.

Date of Survey: October, 2010.



NAD 83 coordinates for this corner:  
Latitude = 47°54'24.01"N Longitude = 113°52'41.35"W  
NOTE: These coordinates are to be used as a search tool only.



CERTIFICATION

I, Steve Cummings  
certify the information shown herein is true and correct.

\_\_\_\_\_  
Signature Ground Party Chief

I, Kurt A. Luebke  
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

\_\_\_\_\_  
Signature of Surveyor & Seal

Date: 11-22-2010 Reg. No. 13237 S

Employer: DJ&A P. C.

