

**INSTRUCTIONS**


1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

**CERTIFIED CORNER RECORDATION**

Corner 1/4 Section 5 T. 30N. R. 31W. P.M.M. Lincoln County  
 Section 4 T. 30N. R. 31W. P.M.M.

Date: October 14, 1986

- 1. ORIGINAL RECORD:** Set a quartzite stone 12X8X6 ins., 8 ins. in the ground for 1/4 sec. cor., marked 1/4 on W. face; from which:
- A pine, 16 ins. diam., bears S. 63°E., 37 lks. dist., marked 1/4 S.B.T.
  - A tamarack, 14 ins. diam., bears N. 56°W., 54 lks. dist., marked 1/4 S.B.T.
- SUBSEQUENT RECORD:** Per Corner Record Book No. 1 Page No. 259 dated January 14, 1972 the original corner was destroyed by construction and a steel rod was set, from which:
- A Cottonwood, 10 ins. diam., bears S. 37°W., 26.6 feet dist., marked 1/4 W.
  - A Cottonwood, 10 ins. diam., bears S. 82°40'W., 26.5 feet dist., marked 1/4 W.
- Both trees posted. No Original evidence reported to be found.
- 2. EVIDENCE FOUND:** No Original Evidence found.  
 Found a 5/8 inch diam. steel rod with pile of rocks around, from which:
- A Cottonwood, 15 ins. diam., bears S. 31°W., 28.8 feet dist., marked with visible chainsaw scribing 1/4.
  - A Cottonwood, 19 ins. diam., bears S. 86°E., 26.6 feet dist., with possible overgrown face.
- 3. MONUMENT AND ACCESSORIES SET:** Accepted the 5/8 inch diam. rebar found as the best evidence of the position of this 1/4 Section corner, from which:
- A Cottonwood, 15 ins. diam., bears S. 31°W., 28.8 feet dist., with old face marked: 1/4, scribed new face at base of tree: S. 5 BT
  - A Cottonwood, 15 ins. diam., bears S. 86°E., 26.6 feet dist., with possible overgrown face, scribed new face at base of tree: 1/4 S. 4 BT.
- Both trees tagged and snow blaze, ring and faces painted red. Piled rocks around corner and painted rocks and monument red.



CERTIFICATION

I, L.A. Dolezal  
 certify the information shown herein is true and correct.  
*L.A. Dolezal*  
 Signature Ground Party Chief


I, Melvin D. Lauteren  
 certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)  
*Melvin D. Lauteren*  
 Signature of Surveyor & Seal

Date: 10/18/86 Reg. No. 4232S

Employer: Kootenai Engineering, Inc.

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on October 30, 1986 was noted on the cross-index plat and is assigned page No. 3418, in book No. \_\_\_\_\_

*Janet BF Segel by Bill Buschhoff*  
 County Official Deputy



Cross Index No. C-9 T. \_\_\_\_\_ R. \_\_\_\_\_ PMM • - corner this sheet