

CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)


Record: Set sandstone and dug pits in all four sections.

Found: No evidence of stone or pits. At the approximate proportionate location for the corner, we found a section of railroad rail driven into the ground next to a four-way fence corner. We accept ~~this~~ this evidence as the best evidence of the original location of the corner.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

"E.S. 2989" Tag IN Side of fence post

Date of work: 11-11-75



SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of survey Number 152

Surveyor's Seal

I, S. R. Smith
certify that the information shown herein is true and correct.

S R Smith

Signature of Ground Party Chief


Dean K. Marquardt

I, _____
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Dean K Marquardt

Signature of Surveyor

DIAGRAM OF CORNER:



☐ = Corner recorded on the sheet

E.S. 2989
Registration Number

Office of Clerk and Recorder, County of Linn

This "corner record" was filed for record on the 28th day of January 1976, was noted on the cross-index plat and is assigned page No. 421, in book No. 1

Eleanor L. Vaughn Ma Watson
County Official Deputy